

RESIDENT INPUT SUMMARY
Ed Reidy, Superintendent of Parks
11/15/18 to 12/3/18

Old Business

- 7/16 – A Lake of the Glens resident called to thank us for repaving the walking path, and also inquired about a gap between the new asphalt and the grass that was removed.
 - I left a message informing the caller that the project was ongoing and gaps would be addressed shortly.
 - Update – Filling of gaps has begun.
 - Staff continue to work on this project, with two loads of pulverized black dirt delivered to our yard on November 14.
 - Week of November 19 - Staff filled gaps with dirt, however 2 of the 5 loads we received were wet, clumpy, and difficult to spread.
 - We received 4 phone calls from Brookside Glen residents expressing concerns about the dirt left on the path from the project. I spoke with 3 of the 4 callers, and left a message for the 4th caller. I assured the residents that the project was not yet complete, and staff will continue to remove dirt from the asphalt. Grass seed will be planted in the spring and we will continue filling the gaps with dirt and seed as soon as pulverized black dirt is available.
 - Week of November 26 – Staff removed dirt from the path with the rubber edge plow, the large broom attachment on the Skid Steer, and the new backpack blower.
 - December 3 – Staff re-swept the path with the large broom attachment on the Skid Steer.

- 8/1 – An Indian Boundary South resident’s son called to ask about standing water behind his mother’s fence. We discussed a drainage project the District has been planning for some time that will address the low wet area. I told him it would most likely be a late fall / early winter project.
 - Our directional bore contractor will provide an estimate to run a line under the path and daylight out on the bottom of the hill.
 - November 26 – The catch basin was ordered.
 - November 29 – The J.U.L.I.E. (utility locate) was requested.

- 11/14 – A Kiwanis Park resident called about how wet the turf was in her yard and the park area behind her property.
 - I informed the resident that I inspected the site, saw the issue, and let her know we will look into it further and try to determine why the area is staying so wet.
 - No new information is available as of this report.